PL530E2 Panel Layout





Power Input Header

GREEN Temp Good

Temp Good LED Indicator GREEN Temp Good

Diver Board Enclosure

Power ON/OFF Slide Switch

Connection Cable

Laser Enable Push Button

PL530 Laser, TEC and Thermistor Enclosure

Optional TEC Temp Adjust Pot

Mounting Screws and Holes

Heater Current Adjust Pot

TH TEC Temp Measure Point

Laser Current Adjust Pot

KL Laser Current Measure Point (mA = 2 x mV)

KH Heater Current Measure Point (mA = 2 x mV)

Laser Enable LED Indicator Green Enabled

Sliding Shutter

Laser Beam Output window