



Use Scope Measuring TP3 to Monitor Delay Angle
<https://youtu.be/x3x1Qvrvbc>

Test 1 Connection Diagram

Verify FC4 Board Delay Angle without SCR and Load

Title		
Size	Number	Revision
A		
Date:	4/26/2021	Sheet of
File:	H:\DATA\Test 1 Connection Diagram Sch	Drawn By: